



# Service Advisory

**TAT SA 12-01**

Issued: 12/02/10

Model SR22 w/ Turbonormalizer

Installed per STC SA10588SC

And SE10589SC

**TO:** Owners, Operators, and Service Centers

**SUBJECT:** Release of Hartzell Engine Technologies Service Bulletin No. 040

**EFFECTIVITY:** Cirrus Design SR22 equipped with a Tornado Alley Turbo Inc. Turbonormalizing System using Hartzell Engine Technologies (Formerly Kelly Aerospace) **Turbochargers**. Any aircraft or engine utilizing new (-0000 series) or rebuilt (-9000 series), turbochargers, manufactured before serial number H-NJL00003 (new) or H-NJR00002 (rebuilt).

---

---

<b>Vendor Contact</b>	Hartzell Engine Technologies Technical Support 1-888-461-6077
<b>Document Number</b>	Service Bulletin No. 040
<b>Date</b>	11/9/10
<b>Subject</b>	Debris found in center housing rotating assemblies (CHRA)
<b>Description</b>	This Service Bulletin is being issued to mandate the cleaning of CHRA center housing of turbochargers according to (HET) Service Bulletin No.040
<b>Compliance</b>	Mandatory: Hartzell Engine Technologies
<b>MANPOWER</b>	One mechanic.

**WARRANTY INFORMATION** Reference Hartzell Engine Technologies Technical Service Bulletin No. 040